#### Workforce

## ALABAMA DEPARTMENT OF WORKFORCE ELEVATOR SAFETY RULES ADMINISTRATIVE CODE

### CHAPTER 480-8-5 BOARD RULINGS

#### TABLE OF CONTENTS

480-8-501	Reserved
480-8-502	Repair
480-8-503	Reserved
480-8-504	Reserved
480-8-505	Lock Boxes

480-8-5-.01 <u>Reserved</u>.

Author:

Statutory Authority:

History:

## 480-8-5-.02 Repair.

(1) All preexisting Escalator Emergency Stop Switches shall be in accordance with ASME A17.1 2013 Edition 6.1.6.3.1. Time for repair/upgrade shall be extended two (2) years from the time of the first inspection in which it was noted. The violation shall be noted in the inspection report, but will not be certificate blocking until the two (2) year grace period has elapsed.

Author: Marvin J. Byrum, Chief Inspector

**Statutory Authority:** Code of Ala. 1975, §25-13-6 (2003).

History: New Rule: Filed September 5, 2017; effective October

20, 2017.

480-8-5-.03 Reserved.

Author:

Statutory Authority:

History:

480-8-5-.04 Reserved.

Author:

Statutory Authority:

History:

# 480-8-5-.05 Lock Boxes.

- (1) In the event a licensed inspector visits a location to perform an annual inspection, and he/she fails to be provided access to the machine room, a certificate blocking violation shall be issued. The certificate blocking violation prevents the owner from receiving an operating certificate. A return visit to clear the violation must be made.
- (2) If the inspector fails to be provided full access to the machine room during the follow-up inspection, a second violation shall be issued requiring a lock box to be installed.
- (3) Once required, a lock box marked "Elevator Personnel Only" shall be installed on the wall outside of the Elevator Machine Room. The lock box will be available for purchase from the Alabama Department of Labor Elevator Inspection Division. The purchase will include the box and one key for the owner. A duplicate key will be made available to the inspector and the elevator maintenance company at cost.
- (4) Failure to comply with this requirement will result in the disconnection of the elevator from service and/or include an additional fine.

Author: Eddie Wiggins, Director Inspections Division Statutory Authority: Code of Ala. 1975, \$25-13-6 (2003). History: New Rule: Published May 31, 2024; effective July 15, 2024.